


Kingston Parish Council

Inspection Report

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

Inspections included in this report


Provider	Lewes District Council	 01/07/2022
Site Name	Kingston Play Area	
Actual Date	01/07/2022 08:08:49	
Inspection Type	Playground-Routine Visual	
Inspector	Nicky Soltermann	
Inspection Status	Completed	

Finding Summary

Kingston Play Area Findings

Asset	Finding Title	Creation Date	Resolve By Date	Risk Level
Parrot See Saw	Item - Broken	28/10/2020 09:28:00	27/11/2020 09:30:00	Medium
Mattas	Surface - Perimeter of Surface Shrunk from Edgings	28/04/2021 14:45:01	26/05/2021 14:47:09	Medium
Wet Pour	Item - Hole(s)	30/06/2021 12:58:11		Medium
Cradle Swing Unit	Surface - Cracking	28/07/2021 10:47:33	11/08/2021 10:50:04	Medium
Mattas	Item - Cracked	31/01/2022 10:57:56	14/02/2022 10:59:22	Medium
Team Swing	Item - Corrosion	25/02/2022 14:43:10	25/03/2022 14:45:03	Medium
Cradle Swing Unit	Item - Corrosion	26/04/2022 13:29:25		Medium
Rope net	Fixtures - Rivets Missing	26/05/2021 12:05:13		Low
Team Swing	Swing - Seat(s) - Damaged	22/12/2021 13:30:44	19/01/2022 13:33:49	Low
Team Swing	Swing - Seat(s) - Damaged	22/12/2021 13:34:08	19/01/2022 13:36:28	Low
Cradle Swing Unit	Item - Rubber damaged/loose/missing	31/01/2022 10:53:00		Low
Cradle Swing Unit	Swing - Seat - Degrading	25/02/2022 14:39:04		Low
Flat Seat	Item - Corrosion	01/07/2022 08:09:15	23/09/2022 08:11:27	Low
Rope net	Item - Missing	27/04/2022 08:53:16	25/05/2022 08:54:07	Not set

Inspection - Kingston Play Area - 01/07/2022 08:08:49

Provider	Lewes District Council	
Site Name	Kingston Play Area	
Actual Date	01/07/2022 08:08:49	
Inspection Type	Playground-Routine Visual	
Inspector	Nicky Soltermann	
Inspection Status	Completed	

Site Name	Kingston Play Area
Address	
Postcode	
Notes	

Findings reported within the Inspection

Flat Seat - Finding

Asset	Flat Seat
Finding Title	Item - Corrosion
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	01/07/2022 08:09:15
Resolve By Date	23/09/2022 08:11:27
Finding Resolved Date	
Risk Level	Low
Finding Notes	Seat needs replacing rubber perished

Finding Photos




Previously Reported Findings (unresolved at time of Inspection)

Cradle Swing Unit - Findings


Asset	Cradle Swing Unit
Finding Title	Item - Corrosion
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	26/04/2022 13:29:25
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Rubber is cracking on swing

Finding Photos



Asset	Cradle Swing Unit
Finding Title	Swing - Seat - Degrading
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	25/02/2022 14:39:04
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Rubber seat is splitting

Finding Photos



Asset	Cradle Swing Unit
Finding Title	Item - Rubber damaged/loose/missing
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	31/01/2022 10:53:00
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Rubber perished around chains

Finding Photos



Asset	Cradle Swing Unit
Finding Title	Surface - Cracking
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	28/07/2021 10:47:33
Resolve By Date	11/08/2021 10:50:04
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Surface underneath the toddler swings is uneven, broken and a trip hazards.

Finding Photos



Mattas - Findings

Asset	Mattas
Finding Title	Item - Cracked
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	No Task
Finding Creation Date	31/01/2022 10:57:56
Resolve By Date	14/02/2022 10:59:22
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Matta surface is spongy and broken. Trip hazard. Needs looking at

Finding Photos



Asset	Mattas
Finding Title	Surface - Perimeter of Surface Shrunk from Edgings
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	28/04/2021 14:45:01
Resolve By Date	26/05/2021 14:47:09
Finding Resolved Date	
Risk Level	Medium
Finding Notes	The surface is cracking and shirinking around edges. Possible trip hazard

Finding Photos



Parrot See Saw - Finding

Asset	Parrot See Saw
Finding Title	Item - Broken
Finding Group	Maintenance
Cause	Unknown
Finding Status	Open
Finding Creation Date	28/10/2020 09:28:00
Resolve By Date	27/11/2020 09:30:00
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Handle broken off. This still has not been repaired

Finding Photos



Rope net - Findings

Asset	Rope net
Finding Title	Item - Missing
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	27/04/2022 08:53:16
Resolve By Date	25/05/2022 08:54:07
Finding Resolved Date	
Risk Level	
Finding Notes	Cap missing

Finding Photos



Asset	Rope net
Finding Title	Fixtures - Rivets Missing
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	26/05/2021 12:05:13
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Caps missing from screws

Finding Photos



Team Swing - Findings

Asset	Team Swing
Finding Title	Item - Corrosion
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	25/02/2022 14:43:10
Resolve By Date	25/03/2022 14:45:03
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Seats need replacing, cracking and chunk of rubber out if one

Finding Photos



Asset	Team Swing
Finding Title	Swing - Seat(s) - Damaged
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	22/12/2021 13:34:08
Resolve By Date	19/01/2022 13:36:28
Finding Resolved Date	
Risk Level	Low
Finding Notes	Swing seat is starting to split

Finding Photos



Asset	Team Swing
Finding Title	Swing - Seat(s) - Damaged
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	No Task
Finding Creation Date	22/12/2021 13:30:44
Resolve By Date	19/01/2022 13:33:49
Finding Resolved Date	
Risk Level	Low
Finding Notes	The rubber is splitting on the two swing seats

Finding Photos



Wet Pour - Finding

Asset	Wet Pour
Finding Title	Item - Hole(s)
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	30/06/2021 12:58:11
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	

Finding Photos

